

PX3 OWNER'S MANUAL ERRATA

Rev. A1-2, September 26, 2014

MAKE THESE CHANGES TO YOUR REV A1 MANUAL

1. **Page 9, PX3 Signal Cabling with KXPA100 Amplifier and KX3 to KXPA100 Adapter Cable:**

Add the following note:

 When used with the KXPA100 Amplifier connected as shown here, the PX3 RS232 data rate must be set to 38400 baud (see menu entry RS232 on page 29).

2. **Page 37, Parts List, Front Panel Board, E850624:** Delete the note that reads:

“One pin has been cut on the 40-pin connector on the reverse side.
This is intentional.”

A few early boards had an unused pin cut off. It is left in place on later boards.